



All-Ignition Service Bulletin

Check Engine Light Remains On After Replacing Distributor

Application: Most vehicles with OBDII (1995 to present)

Symptom: The check engine light is still on after you've replaced the distributor

Cause: Code not cleared from the engine computer

Solution: Some vehicles require that certain trouble codes be cleared manually. Clear the code using an appropriate scan tool. Refer to your vehicle's documentation for more specific information.

***IMPORTANT NOTES:**

- N/A

DATA SOURCE: MITCHELL ON DEMAND 2008, A1-CARDONE 2008, ALL-DATA PRO 2008